Success Story:

NGR used for Failure Mode Detection

KOBOLD

Background:

During a recent project involving the installation of a large reservoir tank for a hydraulic power unit on a dam, the team encountered operational challenges due to excessive dead band issues in their existing solution.

Solution:

To address this, they sought a reliable method for failure mode detection. Accustomed to using products from various suppliers, the team was unaware of cable-type solutions like the NGR. Space limitations prevented the use of rod-based alternatives, leading them to explore RF solutions.

Product Used:

Their current vendor recommended contacting Kobold. Impressed by Kobold's expertise, the team found the perfect fit with the NGR.

Customer Benefits:

Scheduled for delivery to Kobold US and subsequent installation near Lancaster, PA, the team anticipates enhanced performance and customer satisfaction.

Contact Us!

Interested in learning more about the product used in this application? Check out our website or contact us!

www.koboldusa.com

info@koboldusa.com